	MEYLE No.	Referece No.
	014 035 0011/HD	124 351 19 42, 201 351 27 42
Repair kit	014 035 0073/HD	124 350 03 41

Subframe mount

to fit

Mercedes A124, 208 / C124, 208 / S124, 202 / W124, 201, 202

as OE

Problem

Leakage of hydro fluid due to high dynamic strain and small bonding surface

Effect

- Rattling from the rear axle and an overall decline of the handling of the vehicle
- Reduced driving comfort

Solution

Hydro mount replaced by an optimised full-rubber mount with a larger bonding surface

Advantage

No leakage possible and significant longer lifetime without restriction of driving comfort