



COMFORT

particle filter



715816

FH934



PA













WANT TO KNOW MORE?



www.valeo-techassist.com

FOR
HYUNDAI
KIA

ELANTRA IV (06/10 >) / ELANTRA V (03/11 >) / I30 I / I30 II / CARENS IV (03/12 >)
CEE'D II / SPORTY WAGON II (05/12 >)



Valeo Service - Société par Actions simplifiée - Capital de 12 900 000 € - 70, rue Playel, 93285 Saint-Denis Cedex - France - B 306 486 408 RCS Bobigny



COMFORT

particle filter



715816

FH934



PA







WANT TO KNOW MORE?



www.valeo-techassist.com

FOR
HYUNDAI

ELANTRA III (09/06 >)



Valeo Service - Société par Actions simplifiée - Capital de 12 900 000€ - 70, rue Playel, 93285 Saint-Denis Cedex - France - B 306 486 408 RCS Bobigny