

Strut Top Mounting



*To fit Audi A3 / Sportback (OE ref. 1KO 412 331 B)
Seat Altea, Toledo (OE ref. 1KO 412 331B)
Skoda Octavia (OE ref. 1KO 412 331B)
VW Caddy, Golf 5 / Plus, Touran (OE ref. 1KO 412 331 B)*

>> PROBLEM:

Noise and squeaking from the front axle, even with original VW parts.


>> CAUSE:

These problems are caused by poor manufacturing and use of inferior materials. Mostly, the rubber metal compound dissolves due to insufficient vulcanization. This leads to a high failure rate.

>> SOLUTION:

febi bilstein recommends to use the strut top mounting febi 22500 (OE ref. 1KO 412 331 B).

The febi strut top mounting is characterised by the use of high-grade material and professional manufacturing. Material and manufacturing **exceed** the car manufacturers' requirements. febi strut top mountings are also very durable.



febi no. 22500

OE ref. 1KO 412331 B



>> ATTENTION:

The strut top mounting bearing (febi 22498) should also be replaced! The repair kit febi 22502 contains all components which should be replaced, strut top mounting (22500) and ball bearing (22498).



**Repair kit
febi no. 22502**