


DONNEES TECHNIQUES

| | |
|---------------------------------|------------|
| Length [mm] | 765 |
| Number of splines (wheels side) | 22 |
| for vehicles without ABS | |
| (wheels side) CV Joint Ø [mm] | 81 |
| (gearbox side) CV Joint Ø [mm] | 94 |
| Number of mounting bores | 6 |
| Ø mounting holes [mm] | 8 |

PHOTOS




DOCUMENTS

- BT-100** Conseils de montage des cardans
- BT-104** Soufflets et Triaxes FIAT
- BT-105** Soufflets et Triaxes SEAT
- BT-131** Refus des carcasses transmissions

APPLICATIONS

| SEAT | | |
|--|--------|-------------------|
| IBIZA (99-02) (6K2, 6K/GP01) - 1.0 | 50 ch | 08.1999 > 02.2002 |
| IBIZA (99-02) (6K2, 6K/GP01) - 1.4 | 60 ch | 08.1999 > 02.2002 |
| IBIZA (99-02) (6K2, 6K/GP01) - 1.4 16V | 75 ch | 05.2000 > 02.2002 |
| | 100 ch | 08.1999 > 02.2002 |
| IBIZA (99-02) (6K2, 6K/GP01) - 1.6 | 75 ch | 08.1999 > 02.2002 |
| INCA (6K9) - 1.4 16V | 75 ch | 04.2000 > |
| INCA (6K9) - 1.4 i | 60 ch | 11.1995 > |
| INCA (6K9) - 1.6 i | 75 ch | 11.1995 > 05.1998 |
| | 75 ch | 11.1995 > 05.1998 |

| VOLKSWAGEN | | |
|---|-------|-------------------|
| CADDY (96-04) Break (9K9B) - 1.4 | 60 ch | 11.1995 > 01.2004 |
| CADDY (96-04) Break (9K9B) - 1.4 16V | 75 ch | 08.2000 > 01.2004 |
| CADDY (96-04) Camionnette (9K9A) - 1.4 | 75 ch | 08.2000 > 01.2004 |
| CADDY (96-04) Camionnette (9K9A) - 60 1.4 | 60 ch | 11.1995 > 01.2004 |
| FLIGHT 3 volumes (6KV2) - 60 1.4 | 60 ch | 12.1995 > 09.2001 |
| FLIGHT 3 volumes (6KV2) - 75 1.4 16V | 75 ch | 10.1999 > 09.2001 |
| FLIGHT 3 volumes (6KV2) - 75 1.6 | 75 ch | 11.1995 > 09.2001 |
| | 75 ch | 11.1995 > 09.1997 |
| POLO (97-02) Variant (6KV5) - 1.4 | 54 ch | 12.1998 > 09.2001 |
| | 60 ch | 05.1997 > 09.2001 |
| POLO (97-02) Variant (6KV5) - 1.4 16V | 75 ch | 10.1999 > 09.2001 |
| POLO (97-02) Variant (6KV5) - 1.6 | 75 ch | 05.1997 > 09.2001 |

 Avant montage, comparez la pièce reçue à celle d'origine afin de vérifier que la bonne pièce a été choisie et peut être montée sur le véhicule. Le non-respect de cette consigne ou des instructions de montage annule la garantie.