

DONNEES TECHNIQUES

Vehicle Main Current	for vehicles with 12V main current
Rated Power [kW]	1.1
Number of Teeth	9T
Rotation Direction	Anti-clockwise rotation
G/R Reducer	With integrated G/R reducer
Number of mounting bores	3
Plug Type ID	SOL05
	Ø12.5mm fixation holes


PHOTOS



BULLETIN TECHNIQUE TB-05

Ce démarreur n'utilise pas de bobinage en cuivre ou en aluminium, mais utilise des aimants ferreux permanents. Si vous traitez ce démarreur brutalement (chute ou coup de marteau sur le démarreur ou le solénoïde), les aimants se fissureront ou casseront. Ceci entraînant la destruction du démarreur.

This starter doesn't use field coils made from copper or aluminium, but uses ferrite permanent magnets. If you treat this starter roughly (e.g. drop or hit on the starter motor or solenoid with a hammer) the magnets will crack or break. Causing the starter to fail.



DOCUMENTS


BT-130 Refus des carcasses alternateurs/démarreurs

APPLICATIONS

AUDI		
A3 (96-03) (8L1) - 1.6	101 ch	09.1996 > 08.2000
	102 ch	08.2000 >
A3 (96-03) (8L1) - 1.8	125 ch	09.1996 >
A3 (96-03) (8L1) - 1.8 T	150 ch	12.1996 >
	180 ch	12.1998 >
A3 (96-03) (8L1) - 1.8 T quattro	150 ch	12.1996 >
	180 ch	10.1998 >
A3 (96-03) (8L1) - S3 quattro	224 ch	10.2001 >
SEAT		
ALHAMBRA (7V8, 7V9) - 1.8 T 20V	150 ch	10.1997 >
ALHAMBRA (7V8, 7V9) - 2.0 i	115 ch	04.1996 >
CORDOBA (93-99) (6K2/C2) - 1.6 i	75 ch	05.1994 > 06.1999
CORDOBA (93-99) (6K2/C2) - 1.8 i	90 ch	02.1993 > 06.1999
CORDOBA (93-99) (6K2/C2) - 2.0 i	115 ch	02.1993 > 06.1999
CORDOBA (96-02) Vario (6K5) - 1.6	101 ch	06.1999 >
CORDOBA (96-02) Vario (6K5) - 1.6 i	75 ch	05.1997 > 06.1999
IBIZA (93-99) (6K1) - 1.6 i	101 ch	04.1996 > 08.1999
IBIZA (99-02) (6K2, 6K/GP01) - 1.6	101 ch	08.1999 > 02.2002
INCA (6K9) - 1.9 D	64 ch	11.1995 >
LEON (98-06) (1M1) - 1.4 16V	75 ch	11.1999 >
LEON (98-06) (1M1) - 1.6	100 ch	11.1999 >
	102 ch	10.2005 > 06.2006
LEON (98-06) (1M1) - 1.6 16 V	105 ch	09.2000 >
LEON (98-06) (1M1) - 1.8 20V	125 ch	11.1999 >
LEON (98-06) (1M1) - 1.8 20V T	180 ch	11.1999 >
LEON (98-06) (1M1) - 1.8 20V T 4	180 ch	11.1999 >
LEON (98-06) (1M1) - 1.8 T Cupra R	209 ch	02.2002 >
LEON (05-12) (1P1) - 1.4 16V	75 ch	09.2005 >
TOLEDO (99-06) (1M2) - 1.4 16V	75 ch	07.1999 > 05.2006
TOLEDO (99-06) (1M2) - 1.6	100 ch	04.1999 > 09.2000
TOLEDO (99-06) (1M2) - 1.6 16V	105 ch	09.2000 > 05.2006
TOLEDO (99-06) (1M2) - 1.8 20V	125 ch	04.1999 > 05.2006

SKODA		
OCTAVIA (96-10) (1U2) - 1.4 16V	75 ch	09.2000 >
OCTAVIA (96-10) (1U2) - 1.6	101 ch	02.1997 >
	102 ch	11.2000 >
OCTAVIA (96-10) (1U2) - 1.8 T	150 ch	08.1997 >
OCTAVIA (96-10) (1U2) - 1.8 T 4x4	150 ch	05.2001 >
OCTAVIA (96-10) (1U2) - 2.0	116 ch	04.1999 >
OCTAVIA (96-10) Combi (1U5) - 1.4 16V	75 ch	08.2000 >
OCTAVIA (96-10) Combi (1U5) - 1.6	101 ch	07.1998 >
	102 ch	09.2000 >
OCTAVIA (96-10) Combi (1U5) - 1.8 T	150 ch	07.1998 >
OCTAVIA (96-10) Combi (1U5) - 1.8 T 4x4	150 ch	05.2001 >
OCTAVIA (96-10) Combi (1U5) - 2.0	116 ch	04.1999 >
OCTAVIA (96-10) Combi (1U5) - 2.0 4x4	116 ch	05.2001 >
SSANGYONG		
KYRON - 2.7 Xdi	165 ch	05.2005 >
MUSSO SPORTS - 2.9 D	120 ch	08.2004 >
VOLKSWAGEN		
BORA (1J2) - 1.4 16V	75 ch	03.2000 > 05.2005
BORA (1J2) - 1.6	101 ch	10.1998 > 05.2005
	102 ch	08.2000 > 05.2005
BORA (1J2) - 1.6 16V	105 ch	05.2000 > 05.2005
BORA (1J2) - 1.8 T	150 ch	05.2000 > 05.2005
BORA (1J2) - 2.0	115 ch	10.1998 > 05.2005
BORA (1J2) - 2.0 4motion	115 ch	04.2000 > 05.2005
BORA Break (1J6) - 1.4 16V	75 ch	09.2001 > 05.2005
BORA Break (1J6) - 1.6	100 ch	05.1999 > 05.2005
	102 ch	08.2000 > 05.2005
BORA Break (1J6) - 1.6 16V	105 ch	02.2000 > 05.2005
BORA Break (1J6) - 1.8 T	150 ch	05.2000 > 05.2005
BORA Break (1J6) - 2.0	115 ch	05.1999 > 05.2005
BORA Break (1J6) - 2.0 4motion	115 ch	04.2000 > 05.2005
CADDY (96-04) Break (9K9B) - 1.6	75 ch	11.1995 > 05.1997
CADDY (96-04) Camionnette (9K9A) - 75 1.6	75 ch	11.1995 > 05.1997
FLIGHT 3 volumes (6KV2) - 75 1.6	75 ch	11.1995 > 09.1997
FLIGHT 3 volumes (6KV2) - 100 1.6	100 ch	12.1995 > 09.2001
GOLF (91-99) (1H1) - 2.0	116 ch	08.1991 > 09.1997
GOLF (91-99) (1H1) - 2.0 Syncro (1HX1)	115 ch	08.1995 > 08.1997
GOLF (97-05) (1J1) - 1.4 16V	75 ch	08.1997 > 06.2005
GOLF (97-05) (1J1) - 1.6	100 ch	08.1997 > 02.2000
	101 ch	02.2001 > 06.2001
	102 ch	08.2000 > 06.2005
	107 ch	08.2003 > 06.2005
GOLF (97-05) (1J1) - 1.6 16V	105 ch	02.2000 > 06.2005
GOLF (97-05) (1J1) - 1.8 4motion	125 ch	05.1998 > 06.2005
GOLF (97-05) (1J1) - 2.0	115 ch	07.1998 > 06.2005
GOLF (97-05) (1J1) - 2.0 4motion	115 ch	10.2000 > 06.2005
GOLF (98-02) Cabriolet (1E7) - 1.6	100 ch	06.1998 > 06.2002
GOLF (98-02) Cabriolet (1E7) - 1.8	75 ch	06.1998 > 06.2002
	90 ch	06.1998 > 06.2002

VOLKSWAGEN		
GOLF (98-02) Cabriolet (1E7) - 2.0	115 ch	06.1998 > 06.2002
GOLF (99-05) Break (1J5) - 1.4 16V	75 ch	05.1999 >
GOLF (99-05) Break (1J5) - 1.6	101 ch	05.1999 > 02.2000
	102 ch	08.2000 >
GOLF (99-05) Break (1J5) - 1.6 16V	105 ch	02.2000 >
GOLF (99-05) Break (1J5) - 2.0	115 ch	05.1999 >
GOLF (99-05) Break (1J5) - 2.0 4motion	115 ch	10.2000 >
NEW BEETLE (97-11) (9C1, 1C1) - 1.8 T	150 ch	10.1999 >
NEW BEETLE (97-11) (9C1, 1C1) - 2.0	115 ch	01.1998 >
NEW BEETLE Cabriolet (1Y7) - 2.0	115 ch	09.2002 >
PASSAT (88-96) (3A2, 35I) - 2.0 16V	136 ch	08.1988 > 09.1993
	150 ch	01.1994 > 08.1996
PASSAT (88-97) Variant (3A5, 35I) - 2.0 16V	150 ch	01.1994 > 05.1997
POLO (97-02) Variant (6KV5) - 1.6	101 ch	05.1997 > 09.2001
SHARAN (95-10) (7M8, 7M9, 7M6) - 1.8 T 20V	150 ch	09.1997 >
SHARAN (95-10) (7M8, 7M9, 7M6) - 2.0	115 ch	09.1995 >
	150 ch	09.1995 > 02.2000

 Avant montage, comparez la pièce reçue à celle d'origine afin de vérifier que la bonne pièce a été choisie et peut être montée sur le véhicule. Le non-respect de cette consigne ou des instructions de montage annule la garantie.