

DONNEES TECHNIQUES


Alternator Charge Current [A]	75
Vehicle Main Current	for vehicles with 12V main current
Type de poulie	PVR6
Belt Pulley Ø [mm]	60
Clamp	M8 B+
Plug Type ID	PLUG381

PHOTOS



BULLETIN TECHNIQUE TB-35

ATTENTION
Veuillez vérifier la
poulie avec celle
de la carcasse




Bornes	
B+	Positive
D+	Trio (Lamp)

DOCUMENTS

BT-130 Refus des carcasses alternateurs/démarrateurs

APPLICATIONS

FIAT		
BRAVA (182) - 1.8 GT 16V (182.BC)	113 ch	10.1995 > 10.2001
BRAVA (182) - 1.9 TD 75 S (182.BF)	75 ch	03.1996 > 10.2001
BRAVA (182) - 1.9 TD 100 S (182.BF)	100 ch	03.1996 > 10.2001
BRAVO (95-01) (182) - 1.8 GT (182.AC)	113 ch	10.1995 > 10.2001
BRAVO (95-01) (182) - 1.9 TD 75 S (182.AF)	75 ch	03.1996 > 10.2001
BRAVO (95-01) (182) - 1.9 TD 100 S (182.AF)	100 ch	03.1996 > 10.2001
MAREA (185) - 1.8 115 16V	113 ch	09.1996 >
MAREA (185) - 1.9 TD 100	100 ch	09.1996 >
MAREA (185) - 1.9 TD 75	75 ch	09.1996 >
MAREA Weekend (185) - 1.9 TD 100	100 ch	09.1996 >

 Avant montage, comparez la pièce reçue à celle d'origine afin de vérifier que la bonne pièce a été choisie et peut être montée sur le véhicule. Le non-respect de cette consigne ou des instructions de montage annule la garantie.